

FINAL ASSEMBLY CHECKLIST

INSTALLING RACKING

- Install racking as specified in the contract drawings by using S-brackets to attach the racking to the side of the vault wall.
- Attach hooks to the racking to hold cables and wires neatly off the vault floor.
- Install the grounding ribbon to the side of the vault.

INSTALLING CONDUITS INTO TERMADUCT[®] END BELLS

- To install a PVC pipe or conduit into a Termaduct end bell, first break through the Termaduct end bell with a hammer.
- Apply PVC pipe glue to the pipe and slide it through the open Termaduct end bell.
- Run the telephone cables through the conduit into the vault.

INSTALLING CONDUITS INTO KNOCKOUTS

- To install PVC pipes or conduits into a knockout, first break through the knockout with a hammer.
- Slide the pipes through the open knockout and seal with grout.